



623 Garrison Avenue  
Room 331  
Fort Smith, AR 72901

**Phone:** (479) 784-2216  
**Fax:** (479) 784-2462  
[planning@fortsmithar.gov](mailto:planning@fortsmithar.gov)

January 25, 2024

The Salvation Army of Fort Smith  
Attn: Captain Bradley Hargis  
301 North 6<sup>th</sup> Street  
Fort Smith, AR 72901

RE: 301 and 323 North 6<sup>th</sup> Street

Dear Captain Hargis:

On January 18, 2024, the Fort Smith Historic District Commission approved your application for a Certificate of Appropriateness to replace the roof at 301 and 323 North 6<sup>th</sup> Street using Timberline HDZ Charcoal Architectural shingles.

Section 19-62-5(h) A certificate of appropriateness issued by the historic district commission shall become void unless work pursuant to the certificate of appropriateness is commenced within one year of the date of issuance of the certificate of appropriateness unless the historic district commission grants an extension to the certificate based on abnormal weather conditions or other circumstances beyond the control of the applicant which have been shown to delay the approved work.

If you have any questions regarding the Certificate of Appropriateness, please do not hesitate to call me at 784-2216.


Sincerely,

A handwritten signature in black ink, appearing to read "Morgan Barnhill".

Morgan Barnhill

Administrative/Preservation Coordinator

C:File



**FORT SMITH HISTORIC DISTRICT COMMISSION  
SPECIAL MEETING  
JANUARY 18, 2024, 5:30 P.M.  
DARBY COMMUNITY CENTER, 220 NORTH 7<sup>TH</sup> STREET**

**AGENDA**

- I. CALL TO ORDER**
- II. ROLL CALL**
- III. STATEMENT OF QUALIFICATIONS**
- IV. CITIZENS FORUM**
- V. PUBLIC HEARING**

**A.** Historic Name: Salvation Army Building      Owner: Salvation Army  
Construction Date: c. 1970                      Style Influence: Standard Commercial 20<sup>th</sup> Century  
Address: 301 North 6<sup>th</sup> Street                      Significance: (5) Non-Significant

**B.** Historic Name: Oglesby Building              Owner: Salvation Army  
Construction Date: c. 1921                      Style Influence: Plain/Traditional  
Address: 323 North 6<sup>th</sup> Street                      Significance: (3) Significant Within a Group Context

- Replace roof

**VI. NEXT MEETING DATES**

Study Session – January 25, 2024 – 5:30 pm  
Regular Meeting – February 1, 2024 – 5:30 pm

**ADJOURN**

**FORT SMITH HISTORIC DISTRICT COMMISSION  
SPECIAL MEETING  
JANUARY 18, 2024, 5:30 P.M.  
DARBY COMMUNITY CENTER, 220 NORTH 7<sup>TH</sup> STREET**

**STAFF REPORT**

**A.** Historic Name: Salvation Army Building      Owner: Salvation Army  
Construction Date: c. 1970      Style Influence: Standard Commercial 20<sup>th</sup> Century  
Address: 301 North 6<sup>th</sup> Street      Significance: (5) Non-Significant

**B.** Historic Name: Oglesby Building      Owner: Salvation Army  
Construction Date: c. 1921      Style Influence: Plain/Traditional  
Address: 323 North 6<sup>th</sup> Street      Significance: (3) Significant Within a Group Context

- Replace roof

301 North 6<sup>th</sup> Street -

Finding:

Section 3.5.2 of the Belle Grove Historic District Design Guidelines recommends to properly maintain roofs and all components. Section 3.5.6 recommends repairing a roof by reinforcing the historic materials which compromise roof features. Section 3.5.14 does not recommend introducing a new roof feature that is not compatible in size, scale, material, and color.

Recommendation:

Based on the Belle Grove Historic District Design Guidelines, staff recommends approval.

323 North 6<sup>th</sup> Street –

Finding:

Section 3.5.2 of the Belle Grove Historic District Design Guidelines recommends to properly maintain roofs and all components. Section 3.5.6 recommends repairing a roof by reinforcing the historic materials which compromise roof features. Section 3.5.14 does not recommend introducing a new roof feature that is not compatible in size, scale, material, and color.

Recommendation:

Based on the Belle Grove Historic District Design Guidelines, staff recommends approval.



***Belle Grove Historic District***

c/o City of Fort Smith Planning Dept.  
P.O. Box 1908 or 623 Garrison Ave., Rm 331  
Fort Smith, AR 72902

**Certificate of Appropriateness Application Form**

*(please use blue or black ink only)*

**PROPERTY LOCATION**

Historic Name of Property The Salvation Army of Fort Smith, Arkansas

Address 301 N. 6th Street, Fort Smith, AR 72901

Lot Number \_\_\_\_\_ Block Number \_\_\_\_\_

**OWNER**

Name The Salvation Army

Address 301 N. 6th Street, Fort Smith, AR 72901 Phone (479) 783-6145

**PERSON FILING APPLICATION, IF OTHER THAN OWNER**

Name \_\_\_\_\_

Address \_\_\_\_\_ Phone \_\_\_\_\_

**BUILDING DATA**

Construction Date: 1963

Type of Construction: Wood Frame \_\_\_\_\_ Brick  Stone \_\_\_\_\_ Other \_\_\_\_\_

**Original Use:**

Single Family Residential \_\_\_\_\_ Multi-Family Residential \_\_\_\_\_

Hotel/Boarding House \_\_\_\_\_ Office \_\_\_\_\_

Commercial/Retail \_\_\_\_\_ Industrial \_\_\_\_\_

Vacant \_\_\_\_\_ Combined Uses \_\_\_\_\_

Other Church / Social Services

**CONCISE DESCRIPTION OF PROPOSED WORK:** (Attach additional papers if necessary)

The grey 3-tab roof will be replaced with a charcoal dimensional roof as a hail storm in April 2023 damaged the existing roof. Please see the attached texture and color for the replacement roof.

**PROJECT ARCHITECT/ENGINEER:**

Name Centimark Corporation

Address

1512 Macon Drive, Little Rock, AR

Phone (615) 991-9217

**MINOR WORK APPROVAL**

\_\_\_\_\_ staff

\_\_\_\_\_ date

Upon being signed and dated above by the Planning Director or designee, this application becomes the Minor Work Certificate of Appropriateness. It is valid until \_\_\_\_\_. Issuance of a Minor Work Certificate shall not relieve the applicant, contractor, tenant, or property owner from obtaining any other permit required by City code or any law. Minor work projects not approved by staff will be forwarded to the Certificate of Appropriateness Committee for review at its next meeting.

**CATEGORIES OF MINOR WORK**

(A) Emergency, temporary maintenance and repair which does not permanently alter the distinctive features of the subject building, structure or property, all required City of Fort Smith permits are obtained, and the owner of the property commits to apply for a certificate of appropriateness to make permanent repairs within thirty (30) days of the date on which the administrative staff grants written approval of the emergency, temporary repair;

(B) The installation of HVAC equipment that is located in the rear or on the side of the property and is entirely screened from public view with wood lattice panels or plantings;

(C) The installation of electrical and telephone panels, cable connections, satellite dishes, gas meters, or window air conditioning units that are located on a building's rear facade;

(D) The installation of a roof ventilation device not larger than twelve inches height and located

on the rear of the building's roof;

(E) The installation of a privacy fence that is made of wood with flat boards in a single row, no taller than six feet, located in the rear of the property and set back from the building's front facade at least one-half the distance between the front facade and the property's rear property line;

(F) Installation of a picket fence that is made of wood, no taller than three (3) feet, with pickets no wider than four (4) inches and spacing between pickets of not more than three (3) inches, and painted white or neutral color;

(G) Removal of a chain link fence;

(H) Installation of storm windows that match the design, configuration, and color of the existing windows;

(I) Repair and replacement of a sidewalk or driveway on public and private property that does not involve a change in size material, and location;

(J) The construction, replacement, or repair of a public street or alley; and,

(K) The painting of or installation of shingles on the roof of any building or structure provided the paint colors or shingle color is consistent with the Commission's adopted list of approved paint and shingle colors for use within the historic district.

## **CERTIFICATE OF APPROPRIATENESS**

**Please include the following items that are application specific:**

### **On Existing Buildings:**

- COMPLETE THE CERTIFICATE OF APPROPRIATENESS APPLICATION FORM
- CURRENT COLOR PHOTOGRAPH OF EXISTING APPEARANCE OF STRUCTURE showing its present condition and the existing materials, colors, and textures.
- ELEVATION DRAWINGS- Dimensional drawings of all elevations showing proposed exterior architectural changes.
- PAINT SAMPLES required when changing color. Provide manufacturer's samples or samples of actual paint. Indicate manufacturer's name and the name of the color.
- SIDING SAMPLE- Provide a piece of the siding or a manufacturer's brochure showing a picture of the siding and indicating the specifications.
- WINDOWS- indicate window frame material- wood, vinyl or aluminum- indicate size and style.
- SHINGLES- Provide a sample of the shingle and manufacturer's name and color of the shingle.
- OTHER EXTERIOR DETAIL NOT LISTED ABOVE. Provide sample of the detail along with the

manufacturer's name and specifications.

**On New Construction:**

- COMPLETE THE CERTIFICATE OF APPROPRIATENESS APPLICATION FORM.
- SITE PLAN OF PROPERTY (Recommended scale: 1 inch= 20 feet) Include location of all structures and outside equipment (trash, mechanical, common mail boxes, walls, fences, external lighting fixtures, existing and proposed structures, etc.) Show parking areas, driveways, walks, and other hard surface areas. Indicate on the site plan, materials to be used. A surveyed drawing of the perimeter of the lot(s) is required for all Category III applications that involve a change of footprint.
- ELEVATION DRAWINGS- Dimensional drawings of all exterior elevations. Show textures, architectural details and materials. An additional drawing showing landscaping is desirable. (Recommended Scale: at least 1/4 inch = 1foot).
- PAINT SAMPLES required when changing color. Provide manufacturer's sample or samples of actual paint. Indicate manufacturer's name and the name of the color.
- SIDING SAMPLE- Provide a piece of the siding or a manufacturer's brochure showing a picture of the siding and indicating the specifications.
- WINDOWS- indicate window frame material- wood, vinyl, or aluminum- indicate size and style.
- SHINGLES- Provide a sample of the shingle and the manufacturer's name and color of the shingle.
- OTHER EXTERIOR DETAIL NOT LISTED ABOVE. Provide sample of the detail along with the manufacturer's name and specifications.

Certificates of Appropriateness are effective immediately upon issuance. Any work done outside the scope of the Certificates of Appropriateness renders it null and void.

I hereby certify I am the owner, agent of the owner, or other person in control of the property and that the information given herein, and as shown on the application and Certificate of Appropriateness, is true and that I am authorized to obtain this Certificate of Appropriateness. I understand that if the construction and/or installation for which this Certificate of Appropriateness is issued, is contrary to the requirements of city codes or regulations, violations must be corrected. Approval by the Historic District Commission does not excuse the applicant, owner or agent from compliance with any other applicable codes, ordinances or policies of the City of Fort Smith unless expressly stated by the Commission or its staff.

***Upon approval of commission, all applicants must purchase a permit from the City Building Inspector.***

**Penalties:** Violation of the ordinance constitute a misdemeanor, and violators upon being found guilty shall be fined not less than \$10 nor more than \$500. Each day that a violation continues to exist shall constitute a separate offense\*\*. (Reference State Act 14-172-204)

\*\* (If cited for violation, applicant may appeal in court)

SIGNATURE OF APPLICANT Bradley Hargis 12/20/2023  
(Date)

The Planning Department will mail notices of hearing on all Certificate of Appropriateness applications to adjacent property owners at least 10 days prior to the date of the hearing and publish a notice of the Historic District Commission at least 1 time in a newspaper serving the population of Fort Smith at least 15 days prior to the hearing date.

Application is: Approved , Denied , Deferred

Reason for approval, denial or deferral:

---

---

---

---

---

---

---

---

  
Signature of Historic District Chair

1/18/24  
Date Action Taken

\_\_\_\_\_  
Date of Issuance





***Belle Grove Historic District***

c/o City of Fort Smith Planning Dept.  
P.O. Box 1908 or 623 Garrison Ave., Rm 331  
Fort Smith, AR 72902

**Certificate of Appropriateness Application Form**

*(please use blue or black ink only)*

**PROPERTY LOCATION**

Historic Name of Property The Salvation Army

Address 323 N. 6th Street, Fort Smith, AR 72901

Lot Number \_\_\_\_\_ Block Number \_\_\_\_\_

**OWNER**

Name The Salvation Army

Address 301 N. 6th Street, Fort Smith, AR 72901 Phone (479) 783-6145

**PERSON FILING APPLICATION, IF OTHER THAN OWNER**

Name \_\_\_\_\_

Address \_\_\_\_\_ Phone \_\_\_\_\_

**BUILDING DATA**

Construction Date: 1961

Type of Construction: Wood Frame \_\_\_\_\_ Brick X Stone \_\_\_\_\_ Other \_\_\_\_\_

**Original Use:**

Single Family Residential \_\_\_\_\_ Multi-Family Residential \_\_\_\_\_

Hotel/Boarding House \_\_\_\_\_ Office X

Commercial/Retail \_\_\_\_\_ Industrial \_\_\_\_\_

Vacant \_\_\_\_\_ Combined Uses \_\_\_\_\_

Other \_\_\_\_\_

**CONCISE DESCRIPTION OF PROPOSED WORK:** (Attach additional papers if necessary)

The current green 3 tab roof will be replaced with a dimensional charcoal due to a hail storm that damaged the roof in April 2023.

**PROJECT ARCHITECT/ENGINEER:**

Name Centimark Corporation

Address

1512 Macon Drive, Little Rock, AR

Phone (615) 991-9217

**MINOR WORK APPROVAL**

\_\_\_\_\_ staff

\_\_\_\_\_ date

Upon being signed and dated above by the Planning Director or designee, this application becomes the Minor Work Certificate of Appropriateness. It is valid until \_\_\_\_\_. Issuance of a Minor Work Certificate shall not relieve the applicant, contractor, tenant, or property owner from obtaining any other permit required by City code or any law. Minor work projects not approved by staff will be forwarded to the Certificate of Appropriateness Committee for review at its next meeting.

**CATEGORIES OF MINOR WORK**

(A) Emergency, temporary maintenance and repair which does not permanently alter the distinctive features of the subject building, structure or property, all required City of Fort Smith permits are obtained, and the owner of the property commits to apply for a certificate of appropriateness to make permanent repairs within thirty (30) days of the date on which the administrative staff grants written approval of the emergency, temporary repair;

(B) The installation of HVAC equipment that is located in the rear or on the side of the property and is entirely screened from public view with wood lattice panels or plantings;

(C) The installation of electrical and telephone panels, cable connections, satellite dishes, gas meters, or window air conditioning units that are located on a building's rear facade;

(D) The installation of a roof ventilation device not larger than twelve inches height and located

on the rear of the building's roof;

(E) The installation of a privacy fence that is made of wood with flat boards in a single row, no taller than six feet, located in the rear of the property and set back from the building's front facade at least one-half the distance between the front facade and the property's rear property line;

(F) Installation of a picket fence that is made of wood, no taller than three (3) feet, with pickets no wider than four (4) inches and spacing between pickets of not more than three (3) inches, and painted white or neutral color;

(G) Removal of a chain link fence;

(H) Installation of storm windows that match the design, configuration, and color of the existing windows;

(I) Repair and replacement of a sidewalk or driveway on public and private property that does not involve a change in size material, and location;

(J) The construction, replacement, or repair of a public street or alley; and,

(K) The painting of or installation of shingles on the roof of any building or structure provided the paint colors or shingle color is consistent with the Commission's adopted list of approved paint and shingle colors for use within the historic district.

## **CERTIFICATE OF APPROPRIATENESS**

**Please include the following items that are application specific:**

### **On Existing Buildings:**

- COMPLETE THE CERTIFICATE OF APPROPRIATENESS APPLICATION FORM
- CURRENT COLOR PHOTOGRAPH OF EXISTING APPEARANCE OF STRUCTURE showing its present condition and the existing materials, colors, and textures.
- ELEVATION DRAWINGS- Dimensional drawings of all elevations showing proposed exterior architectural changes.
- PAINT SAMPLES required when changing color. Provide manufacturer's samples or samples of actual paint. Indicate manufacturer's name and the name of the color.
- SIDING SAMPLE- Provide a piece of the siding or a manufacturer's brochure showing a picture of the siding and indicating the specifications.
- WINDOWS- indicate window frame material- wood, vinyl or aluminum- indicate size and style.
- SHINGLES- Provide a sample of the shingle and manufacturer's name and color of the shingle.
- OTHER EXTERIOR DETAIL NOT LISTED ABOVE. Provide sample of the detail along with the

manufacturer's name and specifications.

**On New Construction:**

- COMPLETE THE CERTIFICATE OF APPROPRIATENESS APPLICATION FORM.
- SITE PLAN OF PROPERTY (Recommended scale: 1 inch= 20 feet) Include location of all structures and outside equipment (trash, mechanical, common mail boxes, walls, fences, external lighting fixtures, existing and proposed structures, etc.) Show parking areas, driveways, walks, and other hard surface areas. Indicate on the site plan, materials to be used. A surveyed drawing of the perimeter of the lot(s) is required for all Category III applications that involve a change of footprint.
- ELEVATION DRAWINGS- Dimensional drawings of all exterior elevations. Show textures, architectural details and materials. An additional drawing showing landscaping is desirable. (Recommended Scale: at least 1/4 inch = 1foot).
- PAINT SAMPLES required when changing color. Provide manufacturer's sample or samples of actual paint. Indicate manufacturer's name and the name of the color.
- SIDING SAMPLE- Provide a piece of the siding or a manufacturer's brochure showing a picture of the siding and indicating the specifications.
- WINDOWS- indicate window frame material- wood, vinyl, or aluminum- indicate size and style.
- SHINGLES- Provide a sample of the shingle and the manufacturer's name and color of the shingle.
- OTHER EXTERIOR DETAIL NOT LISTED ABOVE. Provide sample of the detail along with the manufacturer's name and specifications.

Certificates of Appropriateness are effective immediately upon issuance. Any work done outside the scope of the Certificates of Appropriateness renders it null and void.

I hereby certify I am the owner, agent of the owner, or other person in control of the property and that the information given herein, and as shown on the application and Certificate of Appropriateness, is true and that I am authorized to obtain this Certificate of Appropriateness. I understand that if the construction and/or installation for which this Certificate of Appropriateness is issued, is contrary to the requirements of city codes or regulations, violations must be corrected. Approval by the Historic District Commission does not excuse the applicant, owner or agent from compliance with any other applicable codes, ordinances or policies of the City of Fort Smith unless expressly stated by the Commission or its staff.

***Upon approval of commission, all applicants must purchase a permit from the City Building Inspector.***

**Penalties:** Violation of the ordinance constitute a misdemeanor, and violators upon being found guilty shall be fined not less than \$10 nor more than \$500. Each day that a violation continues to exist shall constitute a separate offense\*\*. (Reference State Act 14-172-204)

\*\* (If cited for violation, applicant may appeal in court)

SIGNATURE OF APPLICANT Bradley Hargis 12/20/2023  
(Date)

The Planning Department will mail notices of hearing on all Certificate of Appropriateness applications to adjacent property owners at least 10 days prior to the date of the hearing and publish a notice of the Historic District Commission at least 1 time in a newspaper serving the population of Fort Smith at least 15 days prior to the hearing date.

Application is: Approved \_\_\_\_\_, Denied \_\_\_\_\_, Deferred \_\_\_\_\_

Reason for approval, denial or deferral:

---

---

---

---

---

---

---

---

\_\_\_\_\_  
*Signature of Historic District Chair*

\_\_\_\_\_  
*Date Action Taken*

\_\_\_\_\_  
*Date of Issuance*






Timberline® HDZ™ Charcoal

# 301 and 323 North 6th Street




1/11/2024, 2:59:02 PM

- Fort Smith City Limits
- Zoning
- Street Labels






# 301 and 323 North 6th Street



1/11/2024, 3:05:18 PM

1:1,200

- Fort Smith City Limits
- Zoning
- Assessor Parcels
- Building Footprints



Esri, HERE, Garmin, INCREMENT P, NGA, USGS



300 N 6th St

Fort Smith, Arkansas



Google Street View

Aug 2019


[See more dates](#)



Google

323 N 6th St

Fort Smith, Arkansas

 Google Street View

Aug 2019

[See more dates](#)



# City of Fort Smith Building Permit

623 Garrison Avenue Suite 405 P.O. Box 1908 Fort Smith, AR 72902 (479)784-2206 Fax - (479)784-1030

PERMIT #	PROJECT ADDRESS	DATE ISSUED	ISSUED BY
BC-08-04394	301 N 6th St	06/16/2008	ed

OWNER INFORMATION	
Name <u>Army Salvation</u>	Home Phone _____
Mailing Address <u>301 N 6th St</u>	<u>Fort Smith AR 72901</u>

CONTRACTOR INFORMATION	
Company Name <u>Braun Construction Services, Inc.</u>	Daytime phone # <u>865 980 0900</u>
Contractor Name <u>Braun Construction Services, Inc.</u>	P.O. Box _____
Mailing Address <u>2143 Payne Ave</u>	<u>Alco TN 37701</u>

SUB CONTRACTOR INFORMATION	
Electrician _____	Plumber _____
Mechanical _____	

CHARACTERISTICS OF WORK	
Work Class <u>Repair</u>	Occupancy Type _____
Occupancy Use <u>Salvation Army</u>	Construction Type _____
Zoning Classification <u>RH</u>	Number of Parking Spaces _____
Number of Units _____	Flood Zone? <u>No</u>
Number of Stories _____	
Total Finished (Heated) Floor Area _____ Sq. Ft.	Full Estimated Value <u>\$ 46000.00</u>

FEES
Total Fees \$ _____

PROPERTY LEGAL DESCRIPTION	
Lot _____	Block _____
Subdivision _____	

DESCRIPTION OF WORK
<b>Replace roof on both structures</b>

NOTICE
Separate permits are required for electrical, plumbing, mechanical, and signs.
I understand that this permit is conditioned upon the correctness of the information I have supplied and may be revoked upon a finding by the Chief Inspection Official that any relevant item of information is substantially incorrect. This permit becomes null and void if work or construction authorized is not commenced within 6 months, or if construction or work is suspended or abandoned for a period of 1 year at any time after work is commenced.
Be advised that compliance with the Arkansas Energy Code is required and it is the responsibility of the applicant to certify compliance.
I hereby certify that I have read and examined this application and know the same to be true and correct. All provisions of laws and ordinances governing this type of work will be complied with whether specified herein or not. The granting of a permit does not presume to give authority or cancel the provisions of any other state or local law regulating construction or the performance of construction.
_____ Signature of owner, contractor or authorized agent      Date

Was this property built prior to 1978?     Yes     No  
 If yes, you are required by U.S. EPA's Renovation, Repair, & Painting rule to be a Lead Safe Certified Firm with the U.S. EPA if performing work that will disturb a painted surface in homes, child care facilities and pre-schools built before 1978.  
 I hereby certify that as owner/contractor, the structure at the above address is not being built to sell.

\_\_\_\_\_  
Signature of owner, contractor or authorized agent      Date

# City of Fort Smith Building Permit

623 Garrison Avenue Suite 405 P.O. Box 1908 Fort Smith, AR 72902 (479)784-2206 Fax - (479)784-1030

PERMIT #	PROJECT ADDRESS	DATE ISSUED	ISSUED BY
<b>BM-08-04395</b>	<b>323 N 6th St</b>	<b>06/16/2008</b>	<b>don</b>

OWNER INFORMATION	
Name <b>Army Salvation</b>	Home Phone _____
Mailing Address <b>301 N 6th St</b>	<b>Fort Smith AR 72901</b>

CONTRACTOR INFORMATION	
Company Name <b>Braun Construction Services, Inc.</b>	Daytime phone# <b>865 980 0900</b>
Contractor Name <b>Braun Construction Services, Inc.</b>	P.O. Box _____
Mailing Address <b>2143 Payne Ave</b>	<b>Alco TN 37701</b>

SUB CONTRACTOR INFORMATION	
Electrician _____	Plumber _____
Mechanical _____	_____

CHARACTERISTICS OF WORK	
Work Class <b>Repair</b>	Occupancy Type _____
Occupancy Use <b>Apartment Building</b>	Construction Type _____
Zoning Classification <b>RH</b>	Number of Parking Spaces _____
Number of Units _____	Flood Zone? <b>No</b>
Number of Stories _____	_____
Total Finished (Heated) Floor Area _____ Sq. Ft.	Full Estimated Value <b>\$ 30000.00</b>

FEES	
Total Fees	\$ _____

PROPERTY LEGAL DESCRIPTION	
Lot _____	Block _____
Subdivision _____	

DESCRIPTION OF WORK
<b>roof</b>

NOTICE
<p>Separate permits are required for electrical, plumbing, mechanical, and signs.</p> <p>I understand that this permit is conditioned upon the correctness of the information I have supplied and may be revoked upon a finding by the Chief Inspection Official that any relevant item of information is substantially incorrect. This permit becomes null and void if work or construction authorized is not commenced within 6 months, or if construction or work is suspended or abandoned for a period of 1 year at any time after work is commenced.</p> <p>Beadvised that compliance with the Arkansas Energy Code is required and it is the responsibility of the applicant to certify compliance.</p> <p>I hereby certify that I have read and examined this application and know the same to be true and correct. All provisions of laws and ordinances governing this type of work will be complied with whether specified herein or not. The granting of a permit does not presume to give authority or cancel the provisions of any other state or local law regulating construction or the performance of construction.</p>
_____ Signature of owner, contractor or authorized agent      Date

Was this property built prior to 1978?     Yes     No

If yes, you are required by U.S. EPA's Renovation, Repair, & Painting rule to be a Lead Safe Certified Firm with the U.S. EPA if performing work that will disturb a painted surface in homes, child care facilities and pre-schools built before 1978.

I hereby certify that as owner/contractor, the structure at the above address is not being built to sell.

\_\_\_\_\_  
 Signature of owner, contractor or authorized agent      Date



# Arkansas Architectural Resources Survey Form

**ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM**

1. Resource Number:

2. NR Eligibility:

01-Eligible 02-Ineligible 03-Listed 05-Arkansas Register Listed  
06-Contributing in a Listed District 08-Contributing in a Potential District

3. Contributing/Non-Contributing:

4. Destroyed: (Y or N)  Date:

### Above for AHPP Use Only

#### Survey Data

5. Date Recorded:

6. Recorded By: M. Ford (Cox McLain  
Environmental Consulting, Inc.)

7. Survey Number:

8. Historic Name: Salvation Army Building

9. Alternate Name: Building at 301 N 6th Street

10. District Name: \_\_\_\_\_

11. Quad Map:

12. Geographic Location: S  T  R

13. UTM Coordinates: Z  E  N

14. Town/Nearest Community: Fort Smith

15. Street Address/Directions to Resource: 301 6TH ST N

16. Owner: SALVATION ARMY

17. Owner Address: 301 N 6TH ST

18. Owner Phone Number: (    )    -

19. Informant Name & Phone Number: \_\_\_\_\_

#### Descriptive Data

20. Threats to Property:  Other: \_\_\_\_\_

- 1-None/Property Stable    2-Neglect/Deterioration    5-Private Development    6-Extractive Industry
- 7-Urban Encroachment    8-Government Activity    9-Other

21. Historic Use:  Other: \_\_\_\_\_

22. Present Use:  Other: \_\_\_\_\_

0101-Single Family Dwelling 0102-Multi-Family Dwelling 0301-General Retail Store 0308-Bank 0309-Office  
0401-Church 0601-School 1200-Cemetery 9800-Structure Abandoned/Unoccupied. 9900-Other

23. Setting:  Other: \_\_\_\_\_

1-Rural, Undisturbed 2-Rural, Built-Up 3-Urban Encroachment 4-Small Town 5-Urban 9-Other

24. Total Number of Site Features:  Metal fence  
(e.g. concrete walls, ponds, statuary) \_\_\_\_\_

25. Total Number of Ancillary Structures:   
(e.g. outbuildings, etc.) \_\_\_\_\_

26. Style Influence: Primary:  Secondary:  Other: \_\_\_\_\_

01-Plain/Traditional 04-Greek Revival 05-Italianate 09-Queen Anne/Eastlake 10-Classical Revival  
15-Craftsman 18-Art Deco 19-Art Moderne 21-Standard Commercial 19<sup>th</sup> Century  
22-Standard Commercial 20<sup>th</sup> Century 24-English Revival 25-Colonial Revival 26-American Foursquare  
29-Ranch 33-Mixed Masonry 35-Folk Victorian 99-Other

27. Plan:  Other: \_\_\_\_\_

01-One Room/Single Pen 03-Double Pen 04-Dogtrot 05-Single Pile w/ Central Hall  
17-Shotgun 99-Other

28. Height:  Other: \_\_\_\_\_

01-One 02-One & One-Half 03-Two 04-Two & One-Half 95-Varied 99-Other

29. Basement/Cellar:  Other: \_\_\_\_\_

1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other

30. Wings and/or Projections: A  B  C  Other: \_\_\_\_\_

01-Rear Shed 02-Rear L 03-Rear T 04-Side 11-Enclosed 12-Rear Room 99-Other

31. Construction: A  B  Other: \_\_\_\_\_

01-Log 06-Frame 08-Brick 10-Steel Frame 11-Concrete Block 12-Reinforced Concrete 99-Other

32. Original Wall Material: A  B  Other: \_\_\_\_\_

33. Present Wall Material: A  B  Other: \_\_\_\_\_

01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick  
07-Stone 10-Stucco 12-Cut Stone 13-Field Stone 14-Asbestos  
16-Concrete Block 17-Wood Shingle 18-Cast Concrete 21-Horizontal Board 23-Vertical Board  
31-Vinyl Siding 32-Aluminum Siding 97-Unknown 98-Original Material 99-Other

34. Roof Types: A  B  C  Other: \_\_\_\_\_

01-Gable 02-Gable w/ Parapet 03-Clipped Gable 04-Gable on Hip 06-Hip 07-Pyramid  
08-Gambrel 09-Mansard 12-Flat 13-Flat w/ Parapet 14-Shed 99-Other

35. Roof Features (if present): A  B  Other: \_\_\_\_\_

01-Dormer(s) 02-Steeple 03-Cupola 04-Cresting 05-Clock Tower 07-Tower/Turret  
08-Belfry 10-Skylight 99-Other

36. Roof Materials: A  B  Other: \_\_\_\_\_

01-Wood 02-Asphalt Shingle 03-Metal 05-Tile 06-Tar Built-up 99-Other

37. Chimney Placement: A  B  C  D  Other: \_\_\_\_\_

1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other

38. Chimney Materials: A  B  C  D  Other: \_\_\_\_\_

1-Brick 4-Cut Stone 5-Field Stone 6-Metal 9-Other

39. Foundation Type: A  Other: \_\_\_\_\_

1-Continuous 2-Piers 4-Enclosed Piers 9-Other

40. Foundation Materials: A  Other: \_\_\_\_\_

1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other

41. Porch Types: A  B  C  Other: \_\_\_\_\_

01-Full, Front 02-Three-quarter, Front 03-One-Bay, Central Front 05-Wrap-around D   
06-Awning 07-One-Half, Front 08-Recessed, Front 09-Side 15-Stoop 99-Other

42. Porch Height (Stories): A  B  C  D  Other: \_\_\_\_\_

1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other

43. Porch Roof Types: A  B  C  D  Other: \_\_\_\_\_

1-Gable 2-Hip 3-Flat 4-Shed 5-Clipped Gable 6-Integral 9-Other

44. Porch Details: A  B  C  Other: \_\_\_\_\_

01-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament D   
08-Columns on Piers 11-Posts 12-Iron Posts 13-Screened-in 14-Iron Railing 99-Other

45. Window Type(s): A  B  C  D  Other: \_\_\_\_\_

1-Double-hung 3-Casement 4-Stationary 6-Hopper 7-Awning 9-Other/Materials

46. Light Pane Arrangement: A  /  B  /  C  /

47. Condition:

1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin

48. Architectural Comments: \_\_\_\_\_

Features: The building features a two-story entrance foyer and has numerous instances of exposed beams with overhang.

Alterations to main resource: storefront altered/replaced; doors replaced; Since 1992, most of the windows have been replaced along with the original shield signage.

**Historic Data:**

49. Architect: Nelson, Laser & Cheyne

50. Builder: \_\_\_\_\_

51. Construction Date:  C-circa D-date  Other: \_\_\_\_\_

52. Historic Context: \_\_\_\_\_

The Salvation Army is the original tenant of the building since its construction in ca. 1970.

53. Ethnic Heritage: A  B  Other: \_\_\_\_\_

01-Asian 02-African American 03-European 04-Hispanic 05-Native American  
06-Early American/Caucasian 99-Other


54. Please rate the level of significance of this property compared to others within survey area:

1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context  
4-Marginal 5-Non-Significant





11317-0012-00021-00  
301 North 6th Street



C Street


Sign

6th Street

Flat



NOTE: PORTION OF REAR ELEVATION NOT VISIBLE FROM PUBLIC ROW



ARKANSAS ARCHITECTURAL RESOURCES FORM

ARKANSAS HISTORIC PRESERVATION PROGRAM

- 1. Resource Number: SBO298
- 2. Survey Number:
- 3. District Name: BELLE GROVE HD
- 4. Contributing/Non-Contributing: NO

ABOVE FOR AHPP USE ONLY

5. Date Recorded: 09, 18, 08

6. Recorded By: STS

GENERAL DATA

- 7. Historic Name: SALVATION ARMY BUILDING
- 8. Alternate Name: N/A
- 9. Quad Map: F105

10. Geographic Location: S 08 T 08N R 32W

11. UTM Coordinates: Z 15 E 370755 N 3917219

12. Town/Nearest Community: Fort Smith

13. Street Address/Directions to Resource: 301 N. 6th St.

14. Street Name: NORTH SIXTH STREET

15. Owner: SALVATION ARMY

16. Owner Address: 301 N. 6th St Fort Smith, AR 72901

17. Owner Phone Number: (501) 783-6145


18. Informant Name & Phone Number: N/A

DESCRIPTIVE DATA

19. Use/Original: 0700 Other:     

20. Use/Present: 0700 Other:     

0101-Single Family Dwelling    0102-Multi-Family Dwelling    0301-General Retail Store  
 0308-Bank    0401-Church    0601-School    9800-Structure Al.../Inocc.    9900-Other



21. Setting:  5 Other: \_\_\_\_\_  
 1-Rural, Undisturbed 2-Rural, Built-Up 3-Urban Encroachment 4-Small Town 5-Urban  
 9-Other

22. Threats to Property:  1 Other: \_\_\_\_\_  
 1-None/Property Stable 2-Neglect/Deterioration 5-Private Development  
 7-Urban Encroachment 9-Other

23. Total Number of Site Features:  0  
 (e.g. concrete walls, ponds, statuary)

24. Total Number of Ancillary Structures:  0  
 (e.g. outbuildings, etc.)

25. Style Influence: Primary:  22 Secondary:  Other: \_\_\_\_\_  
 01-Plain/Traditional 04-Greek Revival 05-Italianate 09-Queen Anne/Eastlake 10-Classical Revival  
 15-Craftsman 19-Art Moderne 24-English Revival 25-Colonial Revival 26-American Foursquare  
 21-Standard Commercial 19<sup>th</sup> Century 22-Standard Commercial 20<sup>th</sup> Century 18-Art Deco 99-Other

26. Plan:  09 Other: \_\_\_\_\_  
 01-One Room/single-pen 03-Double-pen 04-Dogtrot 05-Single Pile w/Central Hall  
 07-Rectangular 08-Square 09-Irregular 11-T-shaped 12-L-shaped 99-Other

27. Height (Stories):  01 Other: \_\_\_\_\_  
 01-One 02-One & One-Half 03-Two 04-Two & One-Half 99-Other

28. Basement/Cellar:  3 Other: \_\_\_\_\_  
 1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other

29. Wings and/or Projections: A  0 B  C  Other: \_\_\_\_\_  
 01-Rear Shed 02-Rear L 03-Rear T 04-Side 05-Prow 08-Bay Projection 99-Other

30. Construction: A  08 B  Other: \_\_\_\_\_  
 01-Log 06-Frame 07-Box 08-Brick 09-Stone 12-Reinforced Concrete 99-Other

31. Wall Material/Original: A  05 B  Other: \_\_\_\_\_

32. Wall Material/Present: A  05 B  Other: \_\_\_\_\_  
 01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick 09-Synthetic Siding  
 10-Stucco 12-Cut Stone 13-Field Stone 14-Asbestos 97-Unknown 99-Other

33. Roof Type(s): A  12 B  01 C  Other: \_\_\_\_\_  
 01-Gable 02-Gable w/Parapet 03-Clipped Gable 04-Gable on Hip 06-Hip  
 07-Pyramid 08-Gambrel 12-Flat 13-Flat w/Parapet 99-Other

34. Roof Features (if present): A  0 B  Other: \_\_\_\_\_  
 01-Dormer(s) 02-Steeple 03-Cupola 04-Cresting 05-Clock Tower 07-Tower/Turret  
 08-Belfry 99-Other

35. Roof Materials: A  06 B  02 Other: \_\_\_\_\_  
 01-Wood 02-Composition Shingle 03-Metal 05-Tile 06-Tar Build-up 99-Other

36. Chimney Placement: A  0 B  C  D  Other: \_\_\_\_\_  
 1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other

37. Chimney Material: A  0 B  C  D  Other: \_\_\_\_\_  
 1-Brick 4-Cut Stone 5-Field Stone 6-Metal 7-Other

38. Foundation Type: A  1 Other: \_\_\_\_\_  
 1-Continuous 2-Piers 9-Other

39. Foundation Material: A  4 Other: \_\_\_\_\_  
 1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other

40. Porch Type(s): A  0 B  C  Other: \_\_\_\_\_  
 01-Full, Front 02-Three-quarter, Front 03-One-Bay, Central Front 05-Wrap-around  
 06-Awning 07-One-Half, Front 08-Recessed, Front 09-Side 10-Full, Rear 99-Other

41. Porch Height (Stories): A  0 B  C  Other: \_\_\_\_\_  
 1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other

42. Porch Roof Type(s): A  0 B  C  Other: \_\_\_\_\_  
 1-Gable 2-Hip 3-Flat 4-Shed 5-Clipped Gable 9-Other

43. Porch Detail(s): A  0 B  C  Other: \_\_\_\_\_  
 10-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament  
 06-Lattice 08-Columns on Piers 11-Posts 13-Screened-in 99-Other

44. Window Type(s): A  4 B  9 C  Other: B: AWNING  
 1-Double-hung 2-Triple-hung 3-Casement 4-Stationary 9-Other

45. Light/Pane Arrangement: A  01 /  00 B  01 /  02 C  /

46. Condition:  2  
 1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin

47. Architectural Comments: n/a

**HISTORIC DATA:**

48. Architect: NELSON, LAsser & CheyME

49. Builder: n/a

50. Construction Date:  C C-circa D-date 1970 Other: \_\_\_\_\_

51. Historic Context: n/a

52. Please rate the level of significance of this property compared to others within survey area:  5  
 1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context  
 4-Marginal 5-Non-Significant

53. Are any significant archeological features located on the property?  N None Known

54. Ethnic Heritage: A  03 B  Other: \_\_\_\_\_  
 01-Asian 02-African American 03-European 04-Hispanic 05-Native American 09-Other

55. NR Eligibility:  2  
 1-Eligible 2-Ineligible 3-Listed 4-De-listed 5-Arkansas Register

56. Destroyed: (Y or N)  N Date:



**DESCRIPTIVE DATA**

18. Use, Original 0404 Other \_\_\_\_\_
19. Use, Present 0404 Other \_\_\_\_\_  
 0101-Single Family Dwelling 0301-General Retail Store 0308-Bank  
 0401-Church 0601-School 9800-Structure Aban/Unocc 9900-Other
20. Setting 5 Other \_\_\_\_\_  
 1-Rural, Undisturbed 2-Rural, Built-Up 3-Urban Encroachment 4-Small Town  
 5-Urban 9-Other
21. Threats to Property 1 Other \_\_\_\_\_  
 1-None/Property Stable 2-Neglect/Deterioration 5-Private Development  
 7-Urban Encroachment 9-Other
22. Total Number of Site Features 0
23. Total Number of Ancillary Structures 0

**DESCRIPTIVE DATA OF PRINCIPAL STRUCTURE**

24. Style Influence: Primary 22 Secondary \_\_\_\_\_ Other \_\_\_\_\_  
 01-Plain/Traditional 04-Greek Revival 05-Italianate 09-Queen Anne/Eastlake  
 15-Craftsman 16-Bungalow 24-English Revival 25-Colonial Revival 99-Other
25. Plan 09 Other \_\_\_\_\_  
 01-One Room/Single-pen 03-Double-pen 04-Dogtrot 05-Single Pile w/Central Hall  
 07-Rectangular 08-Square 09-Irregular 11-T-shaped 12-L-shaped 99-Other
26. Height (Stories) 01  
 01-One 02-One & One-Half 03-Two 04-Two & One-Half 99-Other
27. Basement/Cellar 3 Other \_\_\_\_\_  
 1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other
28. Wings and/or Projections: A \_\_\_\_\_ B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Rear Shed 02-Rear L 03-Rear T 04-Side 05-Prow 08-Bay Projection 99-Other
29. Construction: A 99 B \_\_\_\_\_ Other MASONRY WITH PRE-CAST CONC. ROOF FRAME  
 01-Log 06-Frame 07-Box 08-Brick 09-Stone 12-Reinforced Concrete 99-Other
30. Wall Material, Original: A 05 B \_\_\_\_\_ Other \_\_\_\_\_
31. Wall Material, Present: A 98 B \_\_\_\_\_ Other \_\_\_\_\_  
 01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick 09-Synthetic Siding  
 10-Stucco 12-Cut Stone 13-Field Stone 14-Asbestos 97-Unknown 99-Other
32. Roof Type(s): A 12 B 01 C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Gable 02-Gable w/Parapet 03-Clipped Gable 06-Hip 07-Pyramid 08-Gambrel  
 12-Flat 13-Flat w/Parapet 99-Other
33. Roof Features (if present): A 00 B \_\_\_\_\_ Other \_\_\_\_\_  
 01-Dormer(s) 02-Steeple 03-Cupola 04-Cresting 05-Clock Tower  
 07-Tower/Turret 08-Belfry 99-Other
34. Roof Materials: A 00 B 02 Other \_\_\_\_\_  
 01-Wood 02-Composition Shingle 03-Metal 05-Tile 06-Tar/Built-up 99-Other

35. Chimney Placement: A 0 B \_\_\_\_\_ C \_\_\_\_\_ D \_\_\_\_\_ Other \_\_\_\_\_  
 1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other
36. Chimney Material: A 0 B \_\_\_\_\_ C \_\_\_\_\_ D \_\_\_\_\_ Other \_\_\_\_\_  
 1-Brick 4-Cut Stone 5-Field Stone 6-Metal 9-Other
37. Foundation Type 1 Other \_\_\_\_\_  
 1-Continuous 2-Piers 9-Other
38. Foundation Material 4 Other \_\_\_\_\_  
 1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other
39. Porch Type(s): A 00 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Full, Front 03-One Bay, Central Front 05-Wrap-around 06-Awning 07-One-Half, Front  
 08-Recessed, Front 10-Side 11-Full, Rear 99-Other
40. Porch Height (Stories): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other
41. Porch Roof Type(s): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 1-Gable 2-Hip 3-Flat 4-Shed 9-Other
42. Porch Detail(s): A 00 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament  
 06-Lattice 08-Columns on Piers 11-Posts 99-Other
43. Window Type(s): A 4 B 9 C \_\_\_\_\_ Other ONE AWNING UNDER 2 FIXED LIGHTS  
 1-Double-hung 2-Triple-hung 3-Casement 4-Stationary 9-Other
44. Light/Pane Arrangement: A \_\_\_\_\_ B \_\_\_\_\_
45. Condition 1 Comments: \_\_\_\_\_  
 1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin
46. Architectural Comments: N

**HISTORIC DATA**

47. Architect NELSON, LASER & CHEYNE
48. Builder \_\_\_\_\_
49. Construction Date 6 1970 Comments: \_\_\_\_\_
50. Historic Context \_\_\_\_\_
51. Please rate the level of significance of this property compared to others within your survey area. 5  
 1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context 4-Marginal  
 5-Non-significant
52. Are any significant archeological features located on the property? N




# RESOURCE PHOTOGRAPH SHEET

ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM

Survey Number 032



RESOURCE IDENTIFICATION PRIM Roll # 53 FRAME # 32



RESOURCE IDENTIFICATION \_\_\_\_\_

SB0298

SURVEY NO: SB-0298

COUNTY SEBASTIAN

TOWN FORT SMITH

STREET 303 N. 6TH

CATEGORY Building  Site  Object

COMMON NAME SALVATION ARMY

HISTORIC NAME SALVATION ARMY

OWNERSHIP RECORD

Present Owner SALVATION ARMY

Address \_\_\_\_\_

Ownership Public  Private

Size of Property or Site  X  ,

or \_\_\_\_\_ Acres

Present Use MTG. HALL

HISTORIC DATA

Original Owner SALVATION ARMY

Original Use MTG. HALL

Architect or Builder \_\_\_\_\_

Period or Date of Construction c. 1970

HISTORIC SIGNIFICANCE

National  State  Local

Reasons \_\_\_\_\_

REFERENCES \_\_\_\_\_

(FOR STAFF USE ONLY)

ARCHITECTURAL STYLE \_\_\_\_\_

ARCHITECTURAL SIGNIFICANCE

Priority One \_\_\_\_\_

Priority Two \_\_\_\_\_

Priority Three \_\_\_\_\_

RECORDED BY: \_\_\_\_\_ DATE 7-22-80 NEGATIVE # 15

IDENTIFICATION: \_\_\_\_\_


















# Arkansas Architectural Resources Survey Form

**ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM**

1. Resource Number:

2. NR Eligibility:

01-Eligible 02-Ineligible 03-Listed 05-Arkansas Register Listed  
06-Contributing in a Listed District 08-Contributing in a Potential District

3. Contributing/Non-Contributing:

4. Destroyed: (Y or N)  Date:

### Above for AHPP Use Only

#### Survey Data

5. Date Recorded:

6. Recorded By: M. Ford (Cox McLain  
Environmental Consulting, Inc.)

7. Survey Number:

8. Historic Name: Oglesby Building

9. Alternate Name: Todd Building

10. District Name: \_\_\_\_\_

11. Quad Map:

12. Geographic Location: S  T  R

13. UTM Coordinates: Z  E  N

14. Town/Nearest Community: Fort Smith

15. Street Address/Directions to Resource: 323 6TH ST N

16. Owner: SALVATION ARMY

17. Owner Address: 301 N 6TH ST

18. Owner Phone Number: (  )  -

19. Informant Name & Phone Number: \_\_\_\_\_

#### Descriptive Data

20. Threats to Property:  Other: \_\_\_\_\_

- 1-None/Property Stable    2-Neglect/Deterioration    5-Private Development    6-Extractive Industry
- 7-Urban Encroachment    8-Government Activity    9-Other

21. Historic Use:  Other: \_\_\_\_\_

22. Present Use:  Other: \_\_\_\_\_

0101-Single Family Dwelling 0102-Multi-Family Dwelling 0301-General Retail Store 0308-Bank 0309-Office  
0401-Church 0601-School 1200-Cemetery 9800-Structure Abandoned/Unoccupied. 9900-Other

23. Setting:  Other: \_\_\_\_\_

1-Rural, Undisturbed 2-Rural, Built-Up 3-Urban Encroachment 4-Small Town 5-Urban 9-Other

24. Total Number of Site Features:  Wood fence  
(e.g. concrete walls, ponds, statuary) \_\_\_\_\_

25. Total Number of Ancillary Structures:  Shed  
(e.g. outbuildings, etc.) \_\_\_\_\_

26. Style Influence: Primary:  Secondary:  Other: \_\_\_\_\_

01-Plain/Traditional 04-Greek Revival 05-Italianate 09-Queen Anne/Eastlake 10-Classical Revival  
15-Craftsman 18-Art Deco 19-Art Moderne 21-Standard Commercial 19<sup>th</sup> Century  
22-Standard Commercial 20<sup>th</sup> Century 24-English Revival 25-Colonial Revival 26-American Foursquare  
29-Ranch 33-Mixed Masonry 35-Folk Victorian 99-Other

27. Plan:  Other: \_\_\_\_\_

01-One Room/Single Pen 03-Double Pen 04-Dogtrot 05-Single Pile w/ Central Hall  
17-Shotgun 99-Other

28. Height:  Other: \_\_\_\_\_

01-One 02-One & One-Half 03-Two 04-Two & One-Half 95-Varied 99-Other

29. Basement/Cellar:  Other: \_\_\_\_\_

1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other

30. Wings and/or Projections: A  B  C  Other: \_\_\_\_\_

01-Rear Shed 02-Rear L 03-Rear T 04-Side 11-Enclosed 12-Rear Room 99-Other

31. Construction: A  B  Other: \_\_\_\_\_

01-Log 06-Frame 08-Brick 10-Steel Frame 11-Concrete Block 12-Reinforced Concrete 99-Other

32. Original Wall Material: A  B  Other: C - 00 N/A

33. Present Wall Material: A  B  Other: C - engineered wood paneling

01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick  
07-Stone 10-Stucco 12-Cut Stone 13-Field Stone 14-Asbestos  
16-Concrete Block 17-Wood Shingle 18-Cast Concrete 21-Horizontal Board 23-Vertical Board  
31-Vinyl Siding 32-Aluminum Siding 97-Unknown 98-Original Material 99-Other

34. Roof Types: A  B  C  Other: \_\_\_\_\_

01-Gable 02-Gable w/ Parapet 03-Clipped Gable 04-Gable on Hip 06-Hip 07-Pyramid  
08-Gambrel 09-Mansard 12-Flat 13-Flat w/ Parapet 14-Shed 99-Other

35. Roof Features (if present): A  B  Other: \_\_\_\_\_

01-Dormer(s) 02-Steeple 03-Cupola 04-Cresting 05-Clock Tower 07-Tower/Turret  
08-Belfry 10-Skylight 99-Other

36. Roof Materials: A  B  Other: \_\_\_\_\_

01-Wood 02-Asphalt Shingle 03-Metal 05-Tile 06-Tar Built-up 99-Other



37. Chimney Placement: A  B  C  D  Other: \_\_\_\_\_

1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other

38. Chimney Materials: A  B  C  D  Other: \_\_\_\_\_

1-Brick 4-Cut Stone 5-Field Stone 6-Metal 9-Other

39. Foundation Type: A  Other: \_\_\_\_\_

1-Continuous 2-Piers 4-Enclosed Piers 9-Other

40. Foundation Materials: A  Other: \_\_\_\_\_

1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other

41. Porch Types: A  B  C  Other: E - 25 Balcony; F - 15 Stoop

01-Full, Front 02-Three-quarter, Front 03-One-Bay, Central Front 05-Wrap-around D   
06-Awning 07-One-Half, Front 08-Recessed, Front 09-Side 15-Stoop 99-Other

42. Porch Height (Stories): A  B  C  D  Other: E - N/A; F - N/A

1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other

43. Porch Roof Types: A  B  C  D  Other: E - N/A; F - N/A

1-Gable 2-Hip 3-Flat 4-Shed 5-Clipped Gable 6-Integral 9-Other

44. Porch Details: A  B  C  Other: E - N/A; F - N/A

01-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament D   
08-Columns on Piers 11-Posts 12-Iron Posts 13-Screened-in 14-Iron Railing 99-Other

45. Window Type(s): A  B  C  D  Other: \_\_\_\_\_

1-Double-hung 3-Casement 4-Stationary 6-Hopper 7-Awning 9-Other/Materials

46. Light Pane Arrangement: A  /  B  /  C  /

47. Condition:

1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin

48. Architectural Comments: \_\_\_\_\_

Alterations to main resource: windows replaced – some; wall cladding replaced - some; window opening(s) altered; window opening(s) infilled; window type replaced; awnings removed, front door altered since 1992; staircase on recessed wing removed; staircase on rear facade replaced. Terra cotta tiles replaced w/ asphalt shingles since undated photo on 1980 survey form.

### Historic Data:

49. Architect: \_\_\_\_\_

50. Builder: \_\_\_\_\_

51. Construction Date:  C-circa D-date  Other: \_\_\_\_\_

52. Historic Context: \_\_\_\_\_

According to the 2012 NRHP multiple property documentation form, the first recorded occupant was I.D. Oglesby, beginning in 1911.

53. Ethnic Heritage: A  B  Other: \_\_\_\_\_

01-Asian 02-African American 03-European 04-Hispanic 05-Native American  
06-Early American/Caucasian 99-Other


54. Please rate the level of significance of this property compared to others within survey area:

1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context  
4-Marginal 5-Non-Significant





11317-0012-00021-00  
323 North 6th Street



D Street

6th Street

NOTE: PORTION OF REAR ELEVATION NOT VISIBLE FROM PUBLIC ROW



ARKANSAS ARCHITECTURAL RESOURCES FORM

ARKANSAS HISTORIC PRESERVATION PROGRAM

- 1. Resource Number: SBO304
- 2. Survey Number:
- 3. District Name: BELLE GROVE
- 4. Contributing/Non-Contributing: NC

ABOVE FOR AHPP USE ONLY

5. Date Recorded: 09 / 17 / 00

6. Recorded By: SJS

GENERAL DATA

7. Historic Name:     

8. Alternate Name:     

9. Quad Map: A105

10. Geographic Location: S 08 T 08N R 32W

11. UTM Coordinates: Z 15 E 320789 N 3917257

12. Town/Nearest Community: Fort Smith

13. Street Address/Directions to Resource: 323 N 6th

14. Street Name: North Sixth Street

15. Owner: SALVATION ARMY

16. Owner Address: 301 N 6th Fort Smith, Ark 72901

17. Owner Phone Number: (      )      -     


18. Informant Name & Phone Number:     

(      )      -     

DESCRIPTIVE DATA

- 19. Use/Original: 9900 Other: Reported to be an original CABERN & servants quarters for a house never built
- 20. Use/Present: 0309 Other:

0101-Single Family Dwelling    0102-Multi-Family Dwelling    0301-General Retail Store  
 0308-Bank    0401-Church    0601-School    9800-Structure All Other    9900-Other



N  
N. D STREET

N. 6th STREET

21. Setting: 5 Other: \_\_\_\_\_  
 1-Rural, Undisturbed 2-Rural, Built-Up 3-Urban Encroachment 4-Small Town 5-Urban  
 9-Other
22. Threats to Property: 1 Other: \_\_\_\_\_  
 1-None/Property Stable 2-Neglect/Deterioration 5-Private Development  
 7-Urban Encroachment 9-Other
23. Total Number of Site Features: 0 \_\_\_\_\_  
 (e.g. concrete walls, ponds, statuary)
24. Total Number of Ancillary Structures: 0 \_\_\_\_\_  
 (e.g. outbuildings, etc.)
25. Style Influence: Primary: 01 Secondary: \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Plain/Traditional 04-Greek Revival 05-Italianate 09-Queen Anne/Eastlake 10-Classical Revival  
 15-Craftsman 19-Art Moderne 24-English Revival 25-Colonial Revival 26-American Foursquare  
 21-Standard Commercial 19<sup>th</sup> Century 22-Standard Commercial 20<sup>th</sup> Century 18-Art Deco 99-Other
26. Plan: 07 Other: \_\_\_\_\_  
 01-One Room/single-pen 03-Double-pen 04-Dogtrot 05-Single Pile w/Central Hall  
 07-Rectangular 08-Square 09-Irregular 11-T-shaped 12-L-shaped 99-Other
27. Height (Stories): 03 Other: \_\_\_\_\_  
 01-One 02-One & One-Half 03-Two 04-Two & One-Half 99-Other
28. Basement/Cellar: 3 Other: \_\_\_\_\_  
 1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other
29. Wings and/or Projections: A 02 B \_\_\_\_\_ C \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Rear Shed 02-Rear L 03-Rear T 04-Side 05-Prow 08-Bay Projection 99-Other
30. Construction: A 06 B \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Log 06-Frame 07-Box 08-Brick 09-Stone 12-Reinforced Concrete 99-Other
31. Wall Material/Original: A 06 B \_\_\_\_\_ Other: \_\_\_\_\_
32. Wall Material/Present: A 06 B \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick 09-Synthetic Siding  
 10-Stucco 12-Cut Stone 13-Field Stone 14-Asbestos 97-Unknown 99-Other
33. Roof Type(s): A 06 B 01 C \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Gable 02-Gable w/Parapet 03-Clipped Gable 04-Gable on Hip 06-Hip  
 07-Pyramid 08-Gambrel 12-Flat 13-Flat w/Parapet 99-Other
34. Roof Features (if present): A 0 B \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Dormer(s) 02-Steeple 03-Cupola 04-Cresting 05-Clock Tower 07-Tower/Turret  
 08-Belfry 99-Other
35. Roof Materials: A 02 B \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Wood 02-Composition Shingle 03-Metal 05-Tile 06-Tar Build-up 99-Other
36. Chimney Placement: A 0 B \_\_\_\_\_ C \_\_\_\_\_ D \_\_\_\_\_ Other: \_\_\_\_\_  
 1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other
37. Chimney Material: A 0 B \_\_\_\_\_ C \_\_\_\_\_ D \_\_\_\_\_ Other: \_\_\_\_\_  
 1-Brick 4-Cut Stone 5-Field Stone 6-Metal 7-Other
38. Foundation Type: A 1 Other: \_\_\_\_\_  
 1-Continuous 2-Piers 9-Other

39. Foundation Material: A 3 Other: \_\_\_\_\_  
 1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other
40. Porch Type(s): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Full, Front 02-Three-quarter, Front 03-One-Bay, Central Front 05-Wrap-around  
 06-Awning 07-One-Half, Front 08-Recessed, Front 09-Side 10-Full, Rear 99-Other
41. Porch Height (Stories): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other: \_\_\_\_\_  
 1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other
42. Porch Roof Type(s): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other: \_\_\_\_\_  
 1-Gable 2-Hip 3-Flat 4-Shed 5-Clipped Gable 9-Other
43. Porch Detail(s): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other: \_\_\_\_\_  
 10-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament  
 06-Lattice 08-Columns on Piers 11-Posts 13-Screened-in 99-Other
44. Window Type(s): A 4 B \_\_\_\_\_ C \_\_\_\_\_ Other: \_\_\_\_\_  
 1-Double-hung 2-Triple-hung 3-Casement 4-Stationary 9-Other
45. Light/Pane Arrangement: A 01 / \_\_\_\_\_ B \_\_\_\_\_ / \_\_\_\_\_ C \_\_\_\_\_ / \_\_\_\_\_
46. Condition: 2 \_\_\_\_\_  
 1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin
47. Architectural Comments: rear (west) L wing

**HISTORIC DATA:**

48. Architect: \_\_\_\_\_
49. Builder: \_\_\_\_\_
50. Construction Date: C C-circa D-date 1921 Other: \_\_\_\_\_
51. Historic Context: \_\_\_\_\_
52. Please rate the level of significance of this property compared to others within survey area: 5  
 1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context  
 4-Marginal 5-Non-Significant
53. Are any significant archeological features located on the property? N
54. Ethnic Heritage: A 03 B \_\_\_\_\_ Other: \_\_\_\_\_  
 01-Asian 02-African American 03-European 04-Hispanic 05-Native American 09-Other
55. NR Eligibility: 2 \_\_\_\_\_  
 1-Eligible 2-Ineligible 3-Listed 4-Delisted 5-Arkansas Register
56. Destroyed: (Y or N)   Date: \_\_\_\_\_



DESCRIPTIVE DATA

18. Use, Original 9900 Other REPUTED TO BE A CAR BARN & SERVANTS QUARTERS FOR A HOUSE THAT WAS NEVER BUILT.
19. Use, Present 0309 Other \_\_\_\_\_  
 0101-Single Family Dwelling 0301-General Retail Store 0308-Bank  
 0401-Church 0601-School 9800-Structure Aban/Unocc 9900-Other
20. Setting 5 Other \_\_\_\_\_  
 1-Rural, Undisturbed 2-Rural, Built-Up 3-Urban Encroachment 4-Small Town  
 5-Urban 9-Other
21. Threats to Property 9 Other DETERIORATING ADJACENT PROPERTY  
 1-None/Property Stable 2-Neglect/Deterioration 5-Private Development  
 7-Urban Encroachment 9-Other
22. Total Number of Site Features 000
23. Total Number of Ancillary Structures 01

DESCRIPTIVE DATA OF PRINCIPAL STRUCTURE

24. Style Influence: Primary 01 Secondary \_\_\_\_\_ Other \_\_\_\_\_  
 01-Plain/Traditional 04-Greek Revival 05-Italianate 09-Queen Anne/Eastlake  
 15-Craftsman 16-Bungalow 24-English Revival 25-Colonial Revival 99-Other
25. Plan 07 Other \_\_\_\_\_  
 01-One Room/Single-pen 03-Double-pen 04-Dogtrot 05-Single Pile w/Central Hall  
 07-Rectangular 08-Square 09-Irregular 11-T-shaped 12-L-shaped 99-Other
26. Height (Stories) 03  
 01-One 02-One & One-Half 03-Two 04-Two & One-Half 99-Other
27. Basement/Cellar 3 Other \_\_\_\_\_  
 1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other
28. Wings and/or Projections: A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Rear Shed 02-Rear L 03-Rear T 04-Side 05-Prow 08-Bay Projection 99-Other
29. Construction: A 08 B \_\_\_\_\_ Other \_\_\_\_\_  
 01-Log 06-Frame 07-Box 08-Brick 09-Stone 12-Reinforced Concrete 99-Other
30. Wall Material, Original: A 05 B \_\_\_\_\_ Other \_\_\_\_\_
31. Wall Material, Present: A 98 B \_\_\_\_\_ Other \_\_\_\_\_  
 01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick 09-Synthetic Siding  
 10-Stucco 12-Cut Stone 13-Field Stone 14-Asbestos 97-Unknown 99-Other
32. Roof Type(s): A 06 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Gable 02-Gable w/Parapet 03-Clipped Gable 06-Hip 07-Pyramid 08-Gambrel  
 12-Flat 13-Flat w/Parapet 99-Other
33. Roof Features (if present): A 00 B \_\_\_\_\_ Other \_\_\_\_\_  
 01-Dormer(s) 02-Steeple 03-Cupola 04-Cresting 05-Clock Tower  
 07-Tower/Turret 08-Belfry 99-Other
34. Roof Materials: A 02 B \_\_\_\_\_ Other \_\_\_\_\_  
 01-Wood 02-Composition Shingle 03-Metal 05-Tile 06-Tar/Built-up 99-Other

35. Chimney Placement: A 0 B \_\_\_\_\_ C \_\_\_\_\_ D \_\_\_\_\_ Other \_\_\_\_\_  
 1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior 9-Other
36. Chimney Material: A 0 B \_\_\_\_\_ C \_\_\_\_\_ D \_\_\_\_\_ Other \_\_\_\_\_  
 1-Brick 4-Cut Stone 5-Field Stone 6-Metal 9-Other
37. Foundation Type 1 Other \_\_\_\_\_  
 1-Continuous 2-Piers 9-Other
38. Foundation Material 3 Other \_\_\_\_\_  
 1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other
39. Porch Type(s): A 00 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Full, Front 03-One Bay, Central Front 05-Wrap-around 06-Awning 07-One-Half, Front  
 08-Recessed, Front 10-Side 11-Full, Rear 99-Other
40. Porch Height (Stories): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 1-One 2-One & One-Half 3-Two 4-Two & One-Half 9-Other
41. Porch Roof Type(s): A 0 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 1-Gable 2-Hip 3-Flat 4-Shed 9-Other
42. Porch Detail(s): A 00 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 01-Chamfered Posts 02-Turned Posts 03-Columns 04-Balustrade 05-Wood Ornament  
 06-Lattice 08-Columns on Piers 11-Posts 99-Other
43. Window Type(s): A 4 B \_\_\_\_\_ C \_\_\_\_\_ Other \_\_\_\_\_  
 1-Double-hung 2-Triple-hung 3-Casement 4-Stationary 9-Other
44. Light/Pane Arrangement: A 01 / \_\_\_\_\_ B \_\_\_\_\_ / \_\_\_\_\_
45. Condition 1 Comments: \_\_\_\_\_  
 1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin
46. Architectural Comments: N \_\_\_\_\_

HISTORIC DATA

47. Architect \_\_\_\_\_
48. Builder \_\_\_\_\_
49. Construction Date C 1921 Comments: \_\_\_\_\_
50. Historic Context \_\_\_\_\_
51. Please rate the level of significance of this property compared to others within your survey area. 3  
 1-Very Significant 2-Moderately Significant 3-Significant Within a Group Context 4-Marginal  
 5-Non-significant
52. Are any significant archeological features located on the property? N \_\_\_\_\_






RESOURCE PHOTOGRAPH SHEET

ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM

Survey Number 1035



RESOURCE IDENTIFICATION PRIM Roll # 54 FRAME # 4




RESOURCE IDENTIFICATION PRIM. Roll # 54 FRAME # 6



RESOURCE PHOTOGRAPH SHEET

ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM

Survey Number 035



RESOURCE IDENTIFICATION PRIM. Roll # 54 FRAME # 7



RESOURCE IDENTIFICATION PRIM. Roll # 54 FRAME # 8



ANCILLARY STRUCTURES FORM

ADC-CDC-2303

ARKANSAS HISTORIC PRESERVATION PROGRAM

1. Resource Number 580304
2. Survey Number 035
3. Ancillary ID A

4. Use 9900 Other MULTI-FAMILY HOUSING
0203-Garage/Carriage Hse 0204-Storage/Equip. Shed 0205-Privy 0206-Well/Cistern
0209-Storm Cellar 0302-Smokehouse 0306-Grain Crib 0308-Barn (Feed)
0404-Barn (Livestock) 9700-Unknown 9900-Other

5. Plan 07 Other
06-Square 07-Rectangular 11-Single Crib 12-Side Drive Crib 15-Double Crib Barn
17-Four Crib Barn 18-Transverse Crib 19-Transverse Crib w/Side Additions 99-Other

6. Height (Stories) 03 Other
01-One 02-One & One-Half 03-Two 04-Two & One-Half 99-Other

7. Cellar 3 Other
1-Full 2-Partial 3-No Cellar 8-Unknown 9-Other

8. Construction 08 Other
01-Log 04-Box 05-Brick 06-Stone 08-Concrete Block 12-Frame 99-Other

9. Wall Material 03 Other
01-Log 02-Weatherboard 03-Novelty Siding 04-Board/Batten 05-Brick 12-Cut Stone
13-Field Stone 14-Asbestos 15-Vertical Board 99-Other

10. Roof Type 01 Other
01-Gable 02-Gambrel 03-Hip 04-Pyramid 07-Flat 10-Shed 99-Other

11. Roof Material 02 Other COMPOSITION SHINGLE
01-Wood 02-Asbestos 03-Metal 04-Slate 05-Tile 06-Tar/Built Up 99-Other

12. Chimney Placement A 0 B Other
1-Exterior End 2-Interior End 3-Other Exterior 4-Interior Central 5-Other Interior
9-Other

13. Chimney Material A 0 B Other
1-Brick 5-Cut Stone 6-Field Stone 7-Metal 9-Other

14. Foundation Type 1 Other
1-Continuous 2-Piers 9-Other

15. Foundation Material 5 Other
1-Wood Block 2-Stone 3-Brick 4-Cast Concrete 5-Concrete Block 9-Other

16. Condition 2 Comments
1-Excellent 2-Good 3-Fair 4-Deteriorated 5-Ruin

17. Construction Date 6 1942 Comments

18. Comments

SBO304

SURVEY NO: SB-0304

COUNTY SEBASTIAN

TOWN FORT SMITH

STREET 323 N. 6TH

CATEGORY Building  Site  Object

COMMON NAME \_\_\_\_\_

HISTORIC NAME \_\_\_\_\_

OWNERSHIP RECORD Patrick & Carolyn Todd

Present Owner ~~Patrick & Carolyn~~

Address 323 No. 6th St FS

Ownership Public  Private

Size of Property or Site  Acres

or \_\_\_\_\_ Acres

Present Use OFFICES & APTS.

HISTORIC DATA

Original Owner \_\_\_\_\_

Original Use APTS.

Architect or Builder \_\_\_\_\_

Period or Date of Construction c. 1920

HISTORIC SIGNIFICANCE

National \_\_\_\_\_ State  Local \_\_\_\_\_

Reasons \_\_\_\_\_

REFERENCES \_\_\_\_\_

(FOR STAFF USE ONLY)

ARCHITECTURAL STYLE \_\_\_\_\_

ARCHITECTURAL SIGNIFICANCE

Priority One \_\_\_\_\_

Priority Two \_\_\_\_\_

Priority Three \_\_\_\_\_

RECORDED BY: \_\_\_\_\_ DATE 7-22-80 NEGATIVE # 18

IDENTIFICATION: \_\_\_\_\_


PHYSICAL DESCRIPTION  
 Height in Stories 2 Basement? NO  
 Foundation Material CONC. BRICK  
 Wall Material BRICK  
 Roof Form SINGLE RIDGE  
 Roof Material CLAY TILES  
 INTEGRITY OF ORIGINAL STRUCTURE  
 Unaltered Minor Altered ✓  
 CONDITION  
 Excellent Good ✓ Fair Poor  
 Significant Outbuildings NO

IMPORTANCE TO NEIGHBORHOOD  
 Great Moderate ✓ Minor \_\_\_\_\_  
 INCIDENCE IN AREA  
 Unique Rare ✓ Frequent \_\_\_\_\_  
 REPRESENTATION IN OTHER SURVEYS  
 \_\_\_\_\_  
 IS PRESERVATION/REHAB. IN PROGRESS?  
NO  
 THREATS TO PROPERTY  
NO

ARCHITECTURAL DESCRIPTION

Facade Emphasis: Vertical ✓ Horizontal \_\_\_\_\_ Combined \_\_\_\_\_  
 Symmetrical ✓ Asymmetrical \_\_\_\_\_  
 Appendages: Porches \_\_\_\_\_ Towers \_\_\_\_\_ Cupolas \_\_\_\_\_ Dormers \_\_\_\_\_  
 Location of Main Entrance: Centered \_\_\_\_\_ Right ✓ Left \_\_\_\_\_  
 Plan Shape RECTANGLE  
 Additional Description SEE PHOTO

SKETCH SITE PLAN



Is structure occupied? YES  
 Accessible to Public? NO  
 THEME \_\_\_\_\_

MAP INFORMATION \_\_\_\_\_

COORDINATES  
 Lat. \_\_\_\_\_ Long. \_\_\_\_\_

UTM Reference \_\_\_\_\_

Zone  Easting  Northing















# ANCILLARY STRUCTURES FORM

ADC-CDC-2303

ARKANSAS  
HISTORIC  
PRESERVATION  
PROGRAM

1. Resource Number | SB0304 |  
 2. Survey Number | 11317-0012-00021  
 -00 4 |  
 3. Ancillary ID | C |

4. Use  Other \_\_\_\_\_  
*0203-Garage/Carriage Hse    0204-Storage/Equip. Shed    0205-Privy    0206-Well/Cistern*  
*0209-Storm Cellar    0302-Smokehouse    0306-Grain Crib    0308-Barn (Feed)*  
*0404-Barn (Livestock)    9700-Unknown    9900-Other*
5. Plan  Other \_\_\_\_\_  
*06-Square    07-Rectangular    11-Single Crib    12-Side Drive Crib    15-Double Crib Barn*  
*17-Four Crib Barn    18-Transverse Crib    19-Transverse Crib w/Side Additions    99-Other*
6. Height (Stories)  Other \_\_\_\_\_  
*01-One    02-One & One-Half    03-Two    04-Two & One-Half    99-Other*
7. Cellar  Other \_\_\_\_\_  
*1-Full    2-Partial    3-No Cellar    8-Unknown    9-Other*
8. Construction  Other \_\_\_\_\_  
*01-Log    04-Box    05-Brick    06-Stone    08-Concrete Block    12-Frame    99-Other*
9. Wall Material  Other \_\_\_\_\_  
*01-Log    02-Weatherboard    03-Novelty Siding    04-Board/Batten    05-Brick    12-Cut Stone*  
*13-Field Stone    14-Asbestos    15-Vertical Board    99-Other*
10. Roof Type  Other \_\_\_\_\_  
*01-Gable    02-Gambrel    03-Hip    04-Pyramid    07-Flat    10-Shed    99-Other*
11. Roof Material  Other \_\_\_\_\_  
*01-Wood    02-Asbestos    03-Metal    04-Slate    05-Tile    06-Tar/Built Up    99-Other*
12. Chimney Placement A  B  Other \_\_\_\_\_  
*1-Exterior End    2-Interior End    3-Other Exterior    4-Interior Central    5-Other Interior*  
*9-Other*
13. Chimney Material A  B  Other \_\_\_\_\_  
*1-Brick    5-Cut Stone    6-Field Stone    7-Metal    9-Other*
14. Foundation Type  Other \_\_\_\_\_  
*1-Continuous    2-Piers    9-Other*
15. Foundation Material  Other \_\_\_\_\_  
*1-Wood Block    2-Stone    3-Brick    4-Cast Concrete    5-Concrete Block    9-Other*
16. Condition  Comments \_\_\_\_\_  
*1-Excellent    2-Good    3-Fair    4-Deteriorated    5-Ruin*
17. Construction Date   Comments \_\_\_\_\_
18. Comments  \_\_\_\_\_